

Report No: MAT:TYN18S-01201

Issue No: 1


Material Test Report

Client:
 Gippsland Premium Quarries Pty Ltd
 PO Box 1

Neerim Junction VIC 3831
 AU

Project: QA Testing

Accredited for compliance with ISO/IEC 17025 - Testing. The results of tests, calibrations and/or measurements included in this document are traceable to Australian / national standards.



Y. Pitt

Approved Signatory: Yvonne Pitt
 (Lab Technician)
 NATA Corp. Accreditation #2291, Site #3260
 Date of Issue: 16/05/2018

Sample Details

Sample ID: TYN18S-01201
Client Sample ID: 331
Material: Asphalt Sand
Sample Source: Gippsland Premium Quarries
Site/Sampled From: Stockpile
Date Sampled: 10/05/2018
Specification: No Specification (Sand)
Sampled By: Barry Dickeson
Sampling Method: AS 1141.3.1 (9.4) - Non Backblading
Date Tested: 11/05/2018
Technician: Yvonne Pitt
Sampling Endorsed?: Yes

Particle Size Distribution

Method: AS 1141.11.1
Drying by: Hotplate


Note: Sample Washed

Sieve Size	% Passing	Limits
6.7mm	100	0 – 100
4.75mm	100	0 – 100
2.36mm	93	0 – 100
1.18mm	68	0 – 100
600µm	41	0 – 100
425µm	30	0 – 100
300µm	21	0 – 100
150µm	7	0 – 100
75µm	1.9	0 – 100

Other Test Results

Description	Method	Result	Limits
Moisture Content (%)	AS 1289.2.1.6	5.0	
Sand Equivalent	AS 1289.3.7.1	78	

Chart



Comments

N/A